

FIG. 1 is a perspective view of a container assembly 10, showing a container 12, a lid 14, and a handle 16. The container 12 is shown in an open position, revealing a plurality of compartments 18. The lid 14 is shown in a closed position, and the handle 16 is shown in an open position. The container assembly 10 is shown in a perspective view, and the components are labeled with reference numerals.




FIG. 1

FIG. 2 is a schematic diagram of a mechanical assembly, showing a vertical shaft (556) passing through a series of components. The shaft is supported by a bearing (558) and is connected to a motor (552) via a coupling (550). The motor is mounted on a base (551) and is connected to a power source (532). The assembly is shown in a cross-sectional view, with dashed lines indicating the internal components and the path of the shaft.




FIG. 2




FIG 3